Linac to BLIP Caps

D. Beavis

RSC Meeting August 13, 2015


Goal

- Review Caps with Raster upgrade
- Plan for future upgrades
- NEPA commitment to extend BLIP-Y cap to 10 feet past the tunnel wall

Conclusions

- BLIP-Y Cap will need to extend to 15 feet past the tunnel wall.
- BLIP-Y and BLIP Cap will need to cover the HEBT tunnel till the BLIP spur wall is about >15 feet away from the HEBT wall.
- Blip cap has a notch that needs to be covered.
- Upstream source needs to be understood

The Caps



Linac to BLIP Beam


Table I: Yearly Beam and Losses to BLIP

<u>+</u>			
Parameters	2015	2016	Future
		Phase I	Phase II
		(Raster)	
Average Current	115 <u>uA</u>	140 <u>uA</u>	240 uA
Number of day @ 117 MeV	210	200	~130
Number of day @ 200 MeV	20	30	~100
Losses @750 keV	20%	20%	20%
Losses in linac	0.01%	0.01%	0.01%
Losses in transfer line	0.01%	0.01%	0.01%
Losses at Collimator	0.1 %	0.1%	0.1%

Use 230 days at 240 micro-amps at 200 MeV


More than a factor of 2 conservative

Operating History




During 2003 review—not expected to have increases in operating beam power
See we are a factor of six higher at present

BLIP-Y Cap



Tunnel slope shown wrong—slopes to outside. Same is true for the HEBT tunnel roof.


Simple Collimator model




- Carbon target
- No side shielding-30 cm concrete wall then soil
- 200 MeV
- Transverse analysis
 – Attenuation length 38 cm

Neutrons/cm**2 E>20 MeV

Use exponential to extrapolate fluence



Blip Target



Forward radiation—Attenuation length 71 cm Cap must extend to 1140 cm d/s of target (37 ft)


BNL action Limit

- For Tritium 5% of the DWS
 - Goal is 1000 pCi/l
- Rainwater leaches out a column of soil
- The height of the column depends on geometry including distance
 - Transverse geometry height is 440 cm
 - Forward height is 800 cm


Cap changes

- BLIP-Y --15 feet past tunnel wall.
 - Includes 10 degree angle to surface
 - Can be adjusted for tunnel asymmetry
- Downstream area of pump room must be capped.
 Water flows on HEBT roof to under the caps.
- The notch is too close in the downstream BLIP cap
- Laser Profile Monitor induced Loss
 - Upstream of BLIP bending magnet
 - Does it impact upstream edge of Cap?

Calculation by Seemungal and Yip




BLIP transport




Graphite collimators

BLIP Transport



Raster components in d/s end HEBT tunnel adjacent


Raster




- plunging harp
- 2. 6.50" collimator (internal)
- 3. aluminum bellows (3x)
- 4. raster magnet
- steering magnet (existing)
- 4.25" collimator (internal)
- plunging harp
- laser profile monitor
- 9. laser profile monitor magnet
- 10. beam current transformers (2x)

- 11. beam position monitor
- 12. viewport spool
- 13. beryllium window (existing)
- 14. aluminum bellows (existing)


Blip Target Station



Well Data



Groundwater elevation



The well in 4/15 was 2690 pCi/l rather than less than 1000 Large losses occurred in FY14 due to vacuum leak

summary

- Have design numbers for caps
- One open question on upstream edge
- Well data suggests that there may be a weakness to present system including loss monitors that are not sensitive enough
- Loss monitor upgrade will be in place next year.

Present caps have been doing a good job